

N622MD

1995 Piper PA 46-350P Malibu Mirage

Serial # 46-36016

Airframe : N622MD

1995 Piper PA 46-350P Malibu

Mirage S# 46-36016

2600/hrs. TT - No major damage history - All logs - Annual due:06/20 - IFR due:4/21 - Useful load: 1201.84

Engine Specs: Model TSIO-540-AE2A – Serial #12236-61A

150/Hours since REMAN (3/18)

Prop: Hartzell HC-13YR-1E – Serial #HK-489A

150/Hours since Overhaul (3/18)

Avionics:

Garmin GMA-345 6-Place Intercom

Garmin GNS-530W GPS/COMM/NAV

Bendix/King KY-196

Bendix/King KNS-81

Bendix/King KN-63 DME w/Nav 1 & 2 switching

Bendix/King KCS-55A Slaved H.S.I

Bendix/King KR-87 w/KI-227 slaved indicator

Bendix/King KRA-10A

Bendix/King KFC-150 IFCS w/KC-291 yaw damper

Bendix/King KAS-297B Altitude Preselect & V.S.I.

Bendix/King RDR-2000 VP RADAR

Avidyne EX-500 Multi-function Display

Stratus E.S. Transponder w/traffic & weather

B.F. Goodrich WX-950 Storm-scope

Additional Equipment:

Freon Air Conditioning

Ground Clearance Switch

Copilot's Flight Group

Shadin Digi flow Fuel Totalizer

J.P.I Graphic Engine Monitor

Pilot & Pilot true Airspeed Indicators

LCD Chronometer

Pilot & Copilot Push-to-talk

Electric trim (x2) and standard accessories on yoke

Hard wired for Bose Headsets

De-ice equipped w/Electric Heated Glass Windshield

Power Pac Spoilers

Long Range Fuel

Relief Tube

Locking Fuel Caps

Static Wicks

Courtesy, Taxi, Landing and Strobe Lights

E.I. digital T.I.T. & E.G.T.

Interior: Rated: 8 Original and has been thoroughly detailed thru-out the years shows very well!!

Executive seating in cabin with original buckskin tan leather chairs. Adjustable crew seats with matching sheepskin. Coordinated matching side panels & Tan wool carpeting with an executive writing table! Forward LS & RS storage cabinets! Very nice and tidy!

Exterior: Rated: 8 Original with a professional rejuvenation 3/20! Excellent Condition!!

Overall Juneau White and Sandalwood Tan with Burgundy & Black trim!

COMMENTS:

During flight, 06/02/17, aircraft experienced radio failure when struck by lightning over Denton, TX. Aircraft landed without incident in Monroe, LA.

SEE MAINTENANCE SUMMARY ON LOGS AT RIDGEAIRE.COM

Aircraft specifications are subject to change at any time. This specification sheet is intended as preliminary information and is subject to verification by the purchaser RidgeAire, Inc. 903-586-1521

